

BENNING MA 4

CEE measuring adapter (5-pin/3-pin)

Operating manual Original English version



BENNING

Table of conte	ents	
1.	Application	1
1.1.	General functional description	1
2.	Safety notes and precautions	1
2.1.	Basic information about safety	
2.2.	Symbols used	
3.	Inspection characteristics of the measuring adapter	2
4.	Operating elements	3
5.	Connecting the measuring adapter	5
6.	Testing with the measuring adapter	
6.1.	Testing of three-phase devices with functional test	
6.1.1.	R_{PE} – Protective Conductor Resistance	
6.1.2.	R _{Insu} 1 (LN-PE)	
6.1.3.	R _{Insu} 2 (secPE)	
6.1.4.	R _{insu} 3 (LN-sec.)	
6.1.5.	R _{Insu} 4 (LN-accessible parts without PE)	
6.1.6.	I _{PE} – Protective conductor current	
6.1.7.	I _{Cont} – Contact current	
6.1.8.	I _{Leak} – Device leakage current	
6.1.9.	I _{Leak} – Patient leakage current	
6.1.10.	Functional test	
6.2.	Testing of three-phase devices with alternative leakage current method	
6.2.1.	R_{PE} – Protective conductor resistance	
6.2.2.	$R_{\text{Insu}} = - \text{Fotective conductor resistance}$ $R_{\text{Insu}} = - (LN-PE)$	
6.2.3.	$R_{lnsu} 2 - (secPE)$	
6.2.4.	$R_{lnsu} 3 - (LN-sec.)$	
6.2.5.	R _{Insu} 4 – (LN-accessible parts without PE)	
6.2.6.	I _{PE} – protective conductor current (alt. leak.)	
6.2.7.	I _{Cont} – Contact current (alt. leak.)	
6.2.8.	I _{Leak} – Device leakage current (alt. leak.)	
6.2.9.	IPLeak – Patient leakage current (alt. leak.)	
6.3.	Testing of extension cables	
6.3.1.	R _{PE} – Protective conductor resistance	-
6.3.2.	R _{PE} (e. g. CEE 5-pin, 32 A)	
6.3.3.	R _{Insu} 1 – (LN-PE)	
6.3.4.	Functional test and phase sequence test of cables	
6.3.5.	Function table	
6.4.	Testing of PRCDs and mobile power distributors (RCDs)	18
7.	Internal R_{PE} resistance of the measuring adapter	
8.	Technical data	20
9.	Maintenance	20
10.	Optional accessories	20
11.	Warranty terms	20
12.	Service contacts	21



The measuring adapter helps you to test portable devices. Due to its robust design, it is particularly suited for being used in industrial environments. The measuring adapter is easy to use and thus allows the user to work efficiently and quickly.

You can test devices and extension cables being provided with the following connectors complying with $\mbox{IEC 60309-1}.$

CEE connector:

- 16 A, 50 Hz to 60 Hz, 230 V, L+N+PE, 6h
- 16 A, 50 Hz to 60 Hz, 380 V to 415 V, 3L+N+PE, 6h
- 32 A, 50 Hz to 60 Hz, 380 V to 415 V, 3L+N+PE, 6h

To do this, connect the measuring adapter to an appliance tester for testing portable devices according to

DIN VDE 0701-0702, DIN EN 62353 (VDE 0751-1) or DIN EN 60974-4 (VDE 0544-4).

For connection of the measuring adapter, the appliance tester must be equipped with a shock-proof socket.

Depending on the type of test, a CEE 16 A or 32 A socket may also have to be available. For the CEE 16 A, an optional adapter cable (part no. 044163) is required.

The measuring adapter is suited to be connected to the following appliance testers:

- BENNING ST 725
- BENNING ST 750 / ST 750 A / ST 755 / ST 760
- Devices of other manufacturers

The measuring adapter can be used for the following tests:

- Protective conductor resistance (RPE)
- Insulating resistance (RInsu)
- Functional test and phase sequence test of cables
- Alternative leakage current:
 e. g. protective conductor current (IPE), contact current

(Icont), device leakage current (ILeak), patient leakage current (IPLeak)

- Differential current measuring method
 - IPE
 - Leakage current
- Direct measurement
- Contact current
- Patient leakage current
- Functional test
- Ua
- Welding equipment (ST 760)
- PRCD

The manufacturers' specifications and normative restrictions with regard to alternative leakage current testing and appliance tests must be adhered to.



To do this, thoroughly read the notes stated in the corresponding standard, in the manufacturers' specifications of the test sample and in the operating manual of the appliance tester.

1.1. General functional description

The MA 4 measures the fault current from the test sample using the differential current measuring method. This current is applied on the N and PE line of the tester, so that this fault current can be measured by testers using the differential current measuring method or the direct measuring method with 1 k Ω in the PE of the tester. Deviating measuring resistances in the PE can lead to an incorrect current applied.

2. Safety notes and precautions 2.1. Basic information about safety

The measuring adapter has been designed and tested in compliance with the safety requirements according to **IEC/ EN 61010-1/ VDE 0411-1**. All electrically conductive parts of the housing are connected to the protective conductor system (according to **IEC 61140**, **protection class I**).

The measuring adapter must be used only for testing in environments of measuring category **CAT II** according to **IEC/ EN 61010-1**.

Make sure not to connect and test more than one test sample or one extension cable at a time.

The measuring adapter must be operated under supervision only.

In case of proper use according to the specifications, the safety of both the user and the device is ensured.

Read this operating manual and the operating manual of the appliance tester carefully and thoroughly before using the product. Please observe all instructions of the relevant operating manuals.

The measuring adapter must not be used:

- with the housing being open,
- in case of visible external damage,
 in case of damage of the CEE connectors.
- in case of damage of the CEE connectors, CEE sockets, connecting line or connector,
- in case of strong excessive strain or if the load limits stated in the technical data have been exceeded,
- if the device has been stored under unfavourable conditions for a longer period of time (high exposure to dust, moisture or excessive temperatures).

Non-observance might involve damaging or destruction of the measuring adapter and/or the connected test sample!

2.2. Symbols used



CF

Attention! Danger! Please observe documentation!

🚯 wa

Warning of dangerous voltage!



CAT II Device of measuring category II (max. 300 V)

Ground (voltage against ground)

This symbol on the measuring adapter means that the measuring adapter complies with the relevant EU directives.

The device must not be disposed of via the domestic waste. Further information regarding the WEEE mark can be accessed on the Internet by entering the search term "WEEE".

Instructions



3. Inspection characteristics of the measuring adapter

BENNIN

All tests that can be carried out with your appliance tester for devices with shock-proof socket and that are supported by the measuring adapter can now be performed in an identical way for devices with CEE connector.

Please observe the following aspects during tests using your appliance tester:

 When testing the protective conductor resistance, the value of the measured protective conductor resistance increases by the share caused by the protective conductor line of the measuring adapter.

In case of measuring results near the admissible limiting value, measure the protective conductor resistance of the measuring adapter at the PE connection of its CEE socket and subtract it from the total measuring value of the system.

Alternatively, when using the appliance testers BEN-NING ST 755 / ST 760, a probe calibration can be carried out at the PE connection of the CEE socket.



If the measuring adapter is not used, the probe must then be calibrated again at the PE connection of the appliance tester.

• During insulating resistance or alternative leakage current tests, the three phases L1, L2, L3 and the neutral conductor N of the test sample are shorted.



4. Operating elements



BENNING



BENNING MA 4 measuring adapter

Pos.	Meaning			
1	PE socket for PE test probe (for RPE cable test)			
2	CEE connector: 16 A, 50 Hz to 60 Hz, 380 V to 415 V 3L+N+PE, 6h			
3	CEE connector: 1	6 A, 50 Hz to 60 Hz, 230 V	L+N+PE, 6h	
4	CEE connector: 3	2 A, 50 Hz to 60 Hz, 380 V to 415 V	3L+N+PE, 6h	
5	The mains LED lights up as soon as 230 V are connected to the shock-proof plug.			
6	The LED indications L1-N, L2-N, L3-N light up as soon as the corresponding connections have been established (e. g. via extension cables).			
7	Rotary switch Cable			
8	Rotary switch Function	This rotary selector switch can be used to toggle between cable test, appliance test, appliance test 1 mA and appliance test +3 mA. The IPE currents of 1 mA and 3 mA are only generated when testing with mains voltage. No fault current is generated in the switch position of cable testing!		
9	CEE socket: 16 A, 50 Hz to 60 Hz, 380 V to 415 V CEE socket: 16 A, (3L+N+PE, 6h)		CEE socket: 16 A, (3L+N+PE, 6h)	
10	CEE socket: 16 A, 50 Hz to 60 Hz, 230 V		CEE socket: 16 A, (L+N+PE, 6h)	
11	CEE socket: 32 A, 50 Hz to 60 Hz, 380 V to 415 V		CEE socket: 32 A, (3L+N+PE, 6h)	
12	Shock-proof plug to the tester		Shock-proof plug (types E and F)	
13	Mains connection		CEE 32 A connector (3L+N+PE, 6h)	
14	Mains fuse		T 16 A (6.3 x 32)	
15	Mains connection for tester		Shock-proof socket (type E)	



5. Connecting the measuring adapter

The measuring adapter is equipped with a PTC thermistor as short-circuit protection for cable testing, but not for appliance testing.



Use the measuring adapter only for the intended tests described in this manual.

The manufacturers' specifications or normative restrictions with regard to all tests involved must be adhered to.



To do this, thoroughly read the notes stated in the corresponding standards, in the manufacturers' specifications of the test sample and in the operating manual of the appliance tester.

Before you can start testing, you have to connect the measuring adapter to your appliance tester.

To do this, proceed as follows:

- Make sure that the appliance tester you are using is ready for operation.
- Connect the shock-proof plug of the measuring adapter to the test socket of your appliance tester.

Connecting the measuring adapter to the appliance tester

This is a connection method for appliance testing and cable testing.

For appliance testing, the MA 4 must be connected to the mains. Connect the ST 755 / 760 to the socket of the MA 4.



Connection diagram

6. Testing with the measuring adapter

Testing the adapter for compatibility with thirdparty manufacturers / self-testing the device

In the switch position for appliance testing +1 mA and in the switch position for appliance testing +3 mA, an internal fault current is generated in the MA 4. The fault current becomes detectable for the measuring instruments when 230 V are applied to their test socket. For appliance testing, the MA 4 must be connected to the mains via the CEE 32 A cable. If such a functional test is carried out, no fault current is generated in the switch position for appliance testing without any test samples being connected. By selecting the position for appliance testing +1 mA, a fault current of approx. 1 mA is generated. The fault current depends on the mains voltage. Now, it should be possible to measure this fault current by means of the tester. The fault current is applied on the N conductor

tester. The fault current is applied on the N conductor and on the PE conductor of the measuring instrument.

The current in the N conductor can be determined by any measuring instrument using the differential current measuring method. In order to detect the applied current in the PE, a measuring resistance of 1 k Ω is required. Otherwise, a deviating applied fault current will occur. In case of the ST 755 / 760, this load is automatically selected as soon as three-phase measurement has been activated.

For this test, no test sample may be connected!

Before carrying out the functional test and all tests for which the test sample must be supplied with mains voltage and put into operation, make sure that there are no short-circuits in the test sample within phases L1, L2, L3 and the neutral conductor N! Non-observance might involve damaging or destruction of the measuring adapter and possibly of



(ŝ

the test sample as well! Within the framework of the functional test, it is not possible to determine the values of the power and current consumption of the test sample by means of

the measuring adapter. The displayed values refer to the power consumption of the measuring adapter itself.

BENNING

6.1. Testing of three-phase devices with functional test



For **appliance testing** with the differential current measuring method, the measuring adapter must be connected to the mains via the CEE 32 connector.

6.1.1. R_{PE} – Protective Conductor Resistance

Before testing

resistance of the measuring adapter (see chapter 7). Disconnect the test sample from the mains supply!

Before starting the test, determine the internal RPE

Switch the rotary switch (7) of the **measuring** adapter to position "L1-L2-L3".

The rotary switch (8) of the **measuring adapter** must be set to the position for **appliance testing**.



Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the RPE measurement on your appliance tester.
- Use the test probe to scan all accessible conductive parts of the test sample that are connected to the protective conductor.

As a result, you will obtain the measured R_{PE} value of the test sample.



6.1.2. RInsu 1 (LN-PE)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the Rinsu measurement on your appliance tester.

The insulating resistance is measured between the bridged LN conductor and the PE of the shock-proof socket.

As a result, you will obtain the measured $R_{\mbox{\scriptsize Insu}}$ value of the test sample.







Circuit diagram



6.1.3. R_{Insu} 2 (sec.-PE)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Connect the test probe to the bridged secondary side of the device.
- Start the Rinsu measurement on your appliance tester.

As a result, you will obtain the measured $\mathsf{R}_{\mathsf{Insu}}$ value of the test sample.

The insulating resistance is measured between the PE of the test socket and the secondary side (probe).





Circuit diagram

6.1.4. R_{Insu} 3 (LN-sec.)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Connect the test probe to the bridged secondary side of the device.
- Start the RInsu measurement on your appliance tester.

As a result, you will obtain the measured $R_{\mbox{\scriptsize Insu}}$ value of the test sample.

The insulating resistance is measured between the bridged LN conductor and the secondary side (probe).







6.1.5. R_{Insu} 4 (LN-accessible parts without PE)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the RInsu measurement on your appliance tester.
- Use the test probe to scan all accessible conductive parts of the test sample that are not connected to the protective conductor.

As a result, you will obtain the measured $R_{\mbox{\scriptsize Insu}}$ value of the test sample.

The testing voltage is applied to the bridged L and N conductors and measured to parts without PE connection.



6.1.6. I_{PE} – Protective conductor current

Test procedure (VDE 0701 – 0702 / 0544-4)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the IPE measurement on your appliance tester.

As a result, you will obtain the measured IPE value of the test sample.

The test sample is supplied with mains voltage and must be tested in all switch positions (device functions).

> Please observe inductive/capacitive circuits.







Circuit diagram

6.1.7. I_{Cont} – Contact current

Test procedure (VDE 0701 – 0702 / 0544-4)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- > Start the lcont measurement on your appliance tester.
- The test sample is supplied with mains voltage and must be tested in all switch positions (device functions).
- Use the test probe to scan all accessible conductive parts of the test sample that are not connected to the protective conductor.

As a result, you will obtain the measured $\ensuremath{\mathsf{Icont}}$ value of the test sample.



Connection diagram



Circuit diagram

6.1.8. I_{Leak} – Device leakage current

Test procedure (VDE 0751-1)

Portable test sample

Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.

BENNING

- Start the ILeak measurement on your appliance tester.
 The test sample is supplied with mains voltage and must
- be tested in all switch positions (device functions).
 > Use the test probe to scan all accessible conductive parts and applied parts.

As a result, you will obtain the measured $I_{\mbox{\tiny Leak}}$ value of the test sample.



Connection diagram



9



6.1.9. IPLeak – Patient leakage current

Test procedure (VDE 0751-1)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- > Place the test sample onto an insulated surface.
- Start the IPLeak measurement on your appliance tester.
- The test sample is supplied with mains voltage and must be tested in all switch positions (device functions).
- Use the test probe to scan all accessible conductive parts and applied parts.

As a result, you will obtain the measured IPLeak value of the test sample.





Circuit diagram

6.1.10. Functional test

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- The test sample is supplied with mains voltage and must be tested in all switch positions (device functions).
- > Please observe inductive/capacitive circuits.

As a result, you will obtain the measured I_{PE} value of the test sample.



Connection diagram



6.2. Testing of three-phase devices with alternative leakage current method

The alternative leakage current measuring method must not be carried out as an alternative to insulating resistance measurement. DIN VDE 0702 para. 5.7 expressly points out that measuring the alternative leakage current is an alternative measuring method for measuring the protective conductor current or contact current after an insulating resistance measurement has been passed. Exceptions are devices of protection class I with switched on heating elements and a total connected load of more than 3.5 kW. If such a device does not pass the insulating resistance measurement, it is still considered to be in proper condition if the protective conductor current according to paragraph 5.5 of the mentioned standard is not exceeded.

Symbol:

The **measuring adapter** can be used for measuring the following leakage or fault currents by means of the alternative leakage current measuring method, provided that the test is supported by the connected appliance tester:

- IPE protective conductor current
- Icont contact current
- I_{Leak} device leakage current
- IPLeak patient leakage current



For **alternative leakage current measurement**, the measuring adapter must **not** be connected to the mains via the CEE 32 connector.



Single-phase devices can be tested in the same way.

Before testing



(Ĵ

Disconnect the test sample from the mains supply.

Switch the rotary switch (7) of the **measuring** adapter to position "L1-L2-L3". The rotary switch (8) of the **measuring adapter**

must be set to the position for **appliance testing**.



6.2.1. R_{PE} – Protective conductor resistance Before testing



The rotary switch (8) of the **measuring adapter** must be set to the position for **appliance testing**.

BENNING



Test procedure (VDE 0701-0702)

Portable test sample

- Connect the CEE connector of the test sample to the corresponding CEE socket of the measuring adapter.
- Start the **R**PE measurement on your appliance tester.
- Use the test probe to scan all accessible conductive parts of the test sample that are connected to the protective conductor.

Application

Portable test sample



6.2.2. R_{insu} 1 – (LN-PE)

Before testing



Disconnect the test sample from the mains supply.

Switch the rotary switch (7) of the **measuring** adapter to position "L1-L2-L3". The rotary switch (8) of the **measuring adapter** must be set to the position for appliance testing.



Test procedure (VDE 0701-0702)

Portable test sample

Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.

Start the RInsu measurement on your appliance tester. As a result, you will obtain the measured RInsu value of the test sample.

Application

Portable test sample





6.2.3. R_{Insu} 2 – (sec.-PE)

Portable test sample





6.2.4. R_{Insu} 3 – (LN-sec.)

Portable test sample



Connection diagram







6.2.5. R_{Insu} 4 – (LN-accessible parts without PE)

Portable test sample



6.2.6. I_{PE} – protective conductor current (alt. leak.)

Test procedure (VDE 0701-0702)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the IPE measurement on your appliance tester.

As a result, you will obtain the measured I_{PE} value of the test sample.

Application

Portable test sample



6.2.7. I_{Cont} – Contact current (alt. leak.)

Test procedure (VDE 0701-0702)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the lcont measurement on your appliance tester.
 Contact the test probe(s) of the appliance tester with all
- Contact the test probe(s) of the appliance tester with an necessary measuring points.

As a result, you will obtain the measured $\mathsf{I}_{\mathsf{Cont}}$ value of the test sample.

Application

Portable test sample





Circuit diagram

The contact current is determined for devices of **protection class II** that raise concerns as to an R_{Insu} measurement. Moreover, it is checked to prove the proper insulation capacity under mains voltage. This also applies to devices of **protection class I** with accessible conductive parts which are **not** connected to the protective conductor.



6.2.8. I_{Leak} – Device leakage current (alt. leak.)

Test procedure (VDE 0751-1)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the ILeak measurement on your appliance tester.
- Contact the test probe(s) of the appliance tester with all necessary measuring points.

As a result, you will obtain the measured ILeak value of the test sample.

Application

Portable test sample





Circuit diagram

6.2.9. IPLeak – Patient leakage current (alt. leak.)

Test procedure (VDE 0751-1)

Portable test sample

- Connect the CEE connector of the test sample to the CEE socket of the measuring adapter.
- Start the IPLeak measurement on your appliance tester.
- Contact the test probe(s) of the appliance tester with all necessary measuring points.

As a result, you will obtain the measured IPLeak value of the test sample.

Application

Portable test sample



Connection diagram





6.3. Testing of extension cables

Symbol:

6.3.1. R_{PE} – Protective conductor resistance

(J	For these tests, the MA 4 must be connected to the mains using the CEE 32 connector. The ST 755 / 760 must be connected to the shock-proof socket of the measuring adapter.		
Defere testing			

Before testing

	Before starting the test, determine the internal R _{PE} resistance of the measuring adapter (see chapter 7).
Â	The maximum testing current for RPE measurement is 10 A !

ent is 10 A!

The rotary switch (7) of the measuring adapter can be used in any position for RPE measurement. The rotary switch (8) of the measuring adapter must be set to the position for cable testing.



6.3.2. R_{PE} (e. g. CEE 5-pin, 32 A)

Test procedure (VDE 0701-0702)

Cable test

- Connect both cable connections to the corresponding ۶ CEE sockets of the measuring adapter.
- ⊳ Connect the test probe of your appliance tester to the PE socket (see pos. 1, chapter 4) of the measuring adapter.
- Start the RPE measurement on your appliance tester. ⊳
- Read the RPE measuring result shown on the display of ⊳ the appliance tester.
- ⊳ Subtract the measured RPE value of the measuring adapter from the RPE measuring result of the test sample.

As a result, you will obtain the measured RPE value of the test sample.

≻ Edit the measured RPE value in the appliance tester according to the calculated measuring value.

Application Cable test



Connection diagram



Detailed view





6.3.3. R_{Insu} 1 – (LN-PE)

Before testing

Switch the rotary switch (7) of the measuring adapter to position "L1-L2-L3". The rotary switch (8) of the measuring adapter must be set to the position for cable testing.



Test procedure (VDE 0701-0702)

Cable test

- Connect both cable connections to the corresponding \triangleright CEE connectors of the measuring adapter.
- \triangleright Start the Rinsu measurement on your appliance tester.

Application





Circuit diagram

6.3.4. Functional test and phase sequence test of cables

Before testing

The functional test and phase sequence test of cables can be applied to CEE connecting cables and extension cables.

	-
A	The measuring adapter is supplied with mains voltage.
A	The functional test and phase sequence test of ca- bles may only be carried out after the RPE and RInsu tests

only be carried out after the RPE and RInsu tests have been passed.



For single-phase connecting cables or extension cables (CEE socket, 3-pin), the rotary switch must be set to the locking position "L1" or "L1-L2-L3".

Test procedure

Cable test

Switch the rotary switch (7) of the measuring adapter to position "L1-L2-L3". The rotary switch (8) of the measuring adapter must be set to the position for cable testing.



- Connect both cable connections to the corresponding ≻ CEE sockets of the measuring adapter.
- \triangleright Switch the mains voltage to the test socket of the appliance tester.
- Observe the status LED indication of the corresponding \triangleright CEE socket.
- Compare the indicated LED status with the function table in chapter 6.3.5.
- Successively turn the rotary switch (7) to the positions "L1", "L2" and "L3".

The LED indication must show the status "pass" in any rotary switch position.

Application









6.3.5. Function table

Rotary switch position	L1-N	L2-N	L3-N	Result
	\bigcirc	\bigcirc	\bigcirc	L1, L2, L3 pass
	\bigcirc	\bigcirc	\bigcirc	LN shorted or N inter- rupted
L1, L2, L3	\bigcirc	\bigcirc	\bigcirc	L1 interrupted
	\bigcirc	$\bigcirc \bigcirc \bigcirc \bigcirc \bigcirc$	\bigcirc	L2 interrupted
	\bigcirc	\bigcirc	\bigcirc	L3 interrupted
	\bigcirc	\bigcirc	\bigcirc	L1 pass
L1	\bigcirc	\bigcirc	0	L1-N shorted <u>or</u> L1 or N interrupted
L1	\bigcirc	\bigcirc	\circ	L1-L2 shorted
	\bigcirc	Ō	$\overline{\circ}$	L1-L3 shorted
	\bigcirc	\bigcirc	\bigcirc	L2 pass
L2	\bigcirc	\bigcirc	0	L2-N shorted <u>or</u> L2 or N interrupted
	\bigcirc	\bigcirc	\bigcirc	L1-L2 shorted
	\bigcirc	\bigcirc	\bigcirc	L2-L3 shorted
	\bigcirc	\bigcirc	\bigcirc	L3 pass
L3	\bigcirc	\bigcirc	\bigcirc	L3-N shorted <u>or</u> L3 or N interrupted
	\bigcirc	\bigcirc	\bigcirc	L1-L3 shorted
	\bigcirc	\bigcirc	\bigcirc	L2-L3 shorted

Remarks concerning the function table



LED status = switched on

LED status = switched off

6.4. Testing of PRCDs and mobile power distributors (RCDs)

A portable residual current protection device (PRCD) provides protection against hazardous body currents in the downstream circuit in case of direct contact. The rated value for the tripping fault current depends on the appliance tester used and on the residual current protection device (RCD) used.

The following PRCDs/RCDs can be tested:

A, B)
to the shock-
g adapter must ST 755 / 760.
internal R _{PE} see chapter 7).
nains supply!
out without r will be de-
g adapter can asurement. ing adapter
iance testing!
adapter must



Application



The PRCD / mobile power distributor (RCD) must be connected to the IEC socket of the ST 755 / 760.

Testing of PRCDs



Connection diagram of PRCDs





Connection diagram of mobile power distributors (RCDs)

Circuit diagram PRCD / power distributor (RCD)



Circuit diagram for connection of PRCDs

The following measurements are supported in combination with the ST 755 / 760:

- Tripping current measurement
- Tripping time measurement
- Test key measurement

7. Internal R_{PE} resistance of the measuring adapter

RPE measuring adapter

- > Start the RPE measurement on your appliance tester.
- Contact the test probe of the appliance tester with the PE contact (pos. 9, pos. 10 and pos. 11, chapter 4 "Operating elements") of the corresponding CEE socket (see the figure "RPE measuring adapter" below).
- Write down the measured RPE value.
- Follow the test procedure Class I, RPE for "portable test samples".

Setup for measuring the internal R_{PE} resistance of the measuring adapter



Connection diagram



Detailed view



8. Technical data

0. recimical (Ιαια		
Nominal voltage		3*400 V ±10 %; 50 Hz – 60 Hz	
Current carrying ca	apacity	32 A three-phase current	
Power consumptio	n	"Mains active" 7 VA, $\cos \phi \sim 0.4$	
Protection class		Protection class I acc. to: EN / IEC 61010-1, VDE 0411-1	
Measuring categor	У	П	
Contamination leve	el	2	
EMC		EN 61326-1	
Measuring range		0.08 mA 10.0 mA AC	
Current accuracy		4 % of the measured value ±40 μA	
Measuring accuracy		6 % of the measured value $\pm 60 \ \mu A$	
Fault current source for the tester		N (differential current measuring method), PE (1 k Ω measuring resistance)	
Current source range		0.08 mA 10.0 mA AC	
Ambient conditions:		Altitudes of up to 2000 m above sea level	
Temperature range	e:		
Operating tempera		0.0 °C to 35.0 °C	
Storage temperatu		-20.0 °C to 60.0 °C	
Max. relative humidity: linearly decreasing non-condensing		80.0 % at 30.0 ℃ 60.0 % at 40.0 ℃	
Protection category		IP 40 with the case being open IP 67 with the case being closed	
Dimensions H x W x D	[mm]	170 x 410 x 350	
Weight		4.2 kg	

9. Maintenance

Designation	Part no.
Measuring adapter	044162

The measuring adapter does not require any special maintenance. Please make sure that the surface near the connector contacts is clean and dry. For cleaning, use a slightly moistened cloth. Do not use any cleaning agents, abrasives or solvents.

10. Optional accessories

Figure	Designation	ltem no.
	Adapter cable for the MA 4 16 A / 400 V CEE connector – 32 A / 400 V CEE coupling, Length: 1 m	044163

11. Warranty terms

The measuring adapter is subject to strict quality control. In case of faults with regard to correct functioning, we grant a manufacturer's warranty of 24 months. Manufacturing faults or material defects shall be eliminated by us free of charge as far as the device shows malfunction without external influence and is returned to us without having been opened. Damages caused by falling or incorrect use are excluded from warranty.



Spare parts management Phone: +49 2871 93-553 E-mail: spareparts@benning.de

General service requests Phone: +49 2871 93-556 E-mail: servicerequests@benning.de

Returns management

Phone: +49 2871 93-554 E-mail: returns@benning.de

Training management

Phone: +49 2871 93-557 E-mail: trainingscenter@benning.de

Technical support

Phone: +49 2871 93-555 E-mail: helpdesk@benning.de







Support / helpdesk

BENNING helpdesk team Phone: +49 2871 93-555 Fax: +49 2871 93-417 E-mail: helpdesk@benning.de Website: www.benning.de