

Ergänzung zur Gebrauchsanleitung Publication No. 1011 "Freigeführte Erdungs- und Kurzschließgeräte" nach DIN VDE 0683 Teil 100 (EN/IEC 61230) und Publication No. 1707 "Erdungsstangen"

1. Anwendung

Die zweipolige Phasenanschlussplatte dient zur Anschlussverdoppelung der Phasenschraubklemme (siehe Fig. 1 bis 5).

Die Phasenplatten dürfen nur in Verbindung mit Phasenschraubklemmen (**mit PK1-Verdrehungsschutz**) verwendet werden (siehe Fig. 3).




Fig. 1 Zweipolare Phasenanschlussplatte
PAP 2 M12 SSM B13

3. Seilanschluss

Der Seilanschluss erfolgt an der Phasenanschlussplatte sowie an der jeweiligen Phasenschraubklemme. Die jeweiligen Anschlußseile müssen mit einem Presskabelschuh Ausführung **PK1** (Verdrehungsschutz) ausgestattet sein. Beim Festschrauben der Sechskantmutter **M12** ist die Sechskantschraube **M12** zu kontern (siehe Fig. 4 sowie Fig. 5).




Fig. 4

2. Montage der Phasenschraubklemmen

Die zweipolare Phasenanschlussplatte an die jeweilige Phasenschraubklemme heranführen und festschrauben. Dabei müssen die beiden Schraubbohrungen deckungsgleich übereinander liegen (siehe Fig. 2).



Fig. 2



Fig. 3




Fig. 5

Ergänzung zur Gebrauchsanleitung Publication No. 1011 "Freigeführte Erdungs- und Kurzschließgeräte" nach DIN VDE 0683 Teil 100 (EN/IEC 61230) und Publication No. 1707 "Erdungsstangen"

1. Anwendung

Die dreipolige Phasenanschlussplatte dient zur Anschluss von drei Phasenschraubklemmen (siehe Fig. 1 bis 5).

Die Phasenanschlussplatten dürfen nur in Verbindung mit Phasenschraubklemmen (**mit PK1-Verdrehungsschutz**) verwendet werden (siehe Fig. 3).




Fig. 1 Dreipolige Phasenanschlussplatte
PAP 3 M12 SSM B13 RB

2. Montage der Phasenschraubklemmen

Die dreipolige Phasenanschlussplatte an die erste Phasenschraubklemme heranführen und fest-schrauben. Dabei müssen die beiden Schraubbohrungen deckungsgleich übereinander liegen (siehe Fig. 2).




Fig. 2



Fig. 3

3. Seilanschluss

Der Seilanschluss erfolgt an der Phasenanschlussplatte sowie an der jeweiligen Phasenschraubklemme. Die jeweiligen Anschlußseile müssen mit einem Presskabelschuh Ausführung **PK1** (Verdrehungsschutz) ausgestattet sein. Beim Festschrauben der Sechskantmutter **M12** ist die Sechskantschraube **M12** zu kontern (siehe Fig. 4 sowie Fig. 5).




Fig. 4




Fig. 5

Supplement to Publication No. 1011 "Portable earthing and short-circuiting devices in accordance with EN/IEC 61230 (DIN VDE 0683 Part 100)" and Publication No. 1707 "Earthing rods"

1. Application

The two-pole phase connecting plate allows to connect two phase screw clamps (see Fig. 1 to Fig. 5).

The phase connecting plates may only be used in conjunction with phase screw clamps (**with PK1 anti-rotation element**) (see Fig 3).




Fig. 1 Two-pole phase connecting plate
PAP 2 M12 SSM B13

3. Cable connection

The cables are connected to the phase connecting plate and the relevant phase screw clamp. The relevant connecting cables must be equipped with a anti-rotation crimped cable lug of type **PK1**. When tightening the **M12** hexagon nut, the **M12** hexagon bolt must be locked (see Fig. 4 and Fig. 5).




Fig. 4

2. Installing the phase screw clamps

Bring the two-pole phase connecting plate to the relevant phase screw clamp and tighten it. To this end, the boreholes must be positioned directly on top of each other (see Fig. 2).




Fig. 2




Fig. 3




Fig. 5

Supplement to Publication No. 1011 "Portable earthing and short-circuiting devices in accordance with EN/IEC 61230 (DIN VDE 0683 Part 100)" and Publication No. 1707 "Earthing rods"

1. Application

The three-pole phase connecting plate allows to connect three phase screw clamps (see Fig. 1 to Fig. 5).

The phase connecting plates may only be used in conjunction with phase screw clamps (**with PK1 anti-rotation element**) (see Fig 3).




Fig. 1 Three-pole phase connecting plate
PAP 3 M12 SSM B13 RB

2. Installing the phase screw clamps

Bring the three-pole phase connecting plate to the first phase screw clamp and tighten it. To this end, the boreholes must be positioned directly on top of each other (see Fig. 2).




Fig. 2




Fig. 3

3. Cable connection

The cables are connected to the phase connecting plate and the relevant phase screw clamp. The relevant connecting cables must be equipped with a anti-rotation crimped cable lug of type **PK1**. When tightening the **M12** hexagon nut, the **M12** hexagon bolt must be locked (see Fig. 4 and Fig. 5).




Fig. 4




Fig. 5